## FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

- 1 .Name of Officer
- 2. Name of School
- 3 .Location with name of Education
- Classification of buildings as specified in Column 4 of application for fitness certificate and size
- Nitha.I.P
- St.Ann's Public School, Eloor
- Eloor, Aluva, Aluva
- Three Storied Building

## **Ground Floor**

 Class room
 1x7.20x6.00x3.70 m

 Chemistry Lab
 1x12.23x7.20x3.70 m

 Reception, Library
 1x12.23x7.20x3.70 m

 Store
 2x 3.4x2.88x3.70 m

## **First Floor**

Class room	3x6x7.20x 3.70 m
Staff room	1x300x7.20x3.70 m
Computer room	1x12.23x 7.20x3.70 m
Physics Lab	1x7.20x6.00x3.70 m
Botany lab	1x12.23x7.20x3.70 m
Room for Guide	1x2.40x2.88x3.70m
Store for Lab	2x3.48x2.88x3.70 m
Second Floor	
Class room	5x7.20x6.00x3.70 m
Class room	1x7.20x6.00x3.70 m
Store for lab	2x3.48x2.88x3.70 m
Class room	1x3.00x7.20x3.70 m
Biology lab	1x12.23x7.20x3.70 m
Room	1x2.40x2.88x3.70

- 5. Period of which the certificate is issued
- 6. Nature of defect if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and windows
  - d) Wood work wrought &put up
  - e)Rock
- f) Flooring
- g) Miscellaneous (Cracks etc.)
- 7) Any major defects noticed which will render the building unsafe in any manner
- 8) Whether the maintenance works have been done properly
- 9) Whether the structure is sound or not for conduting classes

- For the academic year 2025-26
- Nil
- Yes
- Sound under normal weather condition

## Note

- 1. The Stability of the structure should be examined also with reference to location, attitude, Insensity of wind, exposure to flood etc.
- 2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected me on...30/04/2025...and found to be fit conduct classes for the period ...upto and including 31.03.2026..........for the reasons stated above.

Place: Eloor

Date: 03.05.2025

Signature

നിത ഐ. പി. Designation 799526 അസിസ്റ്റന്റ് എഞ്ചിനീയർ

ഏലൂർ നഗരസഭ