

FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

- | | |
|---|---|
| 1 Name of Officer | - Yamuna.P.B |
| 2 Name of School | - St.Ann's Public School,Eloor |
| 3 Location with name of Education | - Eloor - Aluva, Aluva |
| 4 Classification of building as specified in column 4 of application for fitness certificate and size | <ul style="list-style-type: none"> - Three Storied Building <li style="margin-left: 20px;"><u>Ground Floor</u> <li style="margin-left: 40px;">Classroom 1x7.20x6.00x3.70m <li style="margin-left: 40px;">Chemistry lab 1x12.23x7.20x3.70m <li style="margin-left: 40px;">Physics lab 1x12.23x7.20x3.70m <li style="margin-left: 40px;">Store. 2x 2.6 x 2.95x3.70m <li style="margin-left: 20px;"><u>First Floor</u> <li style="margin-left: 40px;">Class room 2x9.23x7.20x3.70m <li style="margin-left: 40px;">Staff room 1x300x7.20x3.70m <li style="margin-left: 40px;">Computer room 1x12.23x7.20x3.70m <li style="margin-left: 40px;">Class room 1x7.20x6.00x3.70m <li style="margin-left: 40px;">Botony lab 1x12.23x7.20x3.70m <li style="margin-left: 40px;">Room for Guide 1x2.40x2.88x3.70m <li style="margin-left: 20px;"><u>Second Floor</u> <li style="margin-left: 40px;">Class room 4x7.20x6.00x3.70m <li style="margin-left: 40px;">Zoology lab 1x7.20x6.00x3.70m <li style="margin-left: 40px;">Store for lab 2x3.48x2.88x3.70m <li style="margin-left: 40px;">Class room 1x3.00x7.20x3.70m <li style="margin-left: 40px;">Staff room 1x12.23x7.20x3.70m <li style="margin-left: 40px;">Room 1x2.40x2.88x3.70 |
| 5 Period of which the certificate is issued | - For the academic year 2023-24 |
| 6 Nature of defect if any | - Nil |
| a) Foundation and basement | - Nil |
| b) Superstructure | - Nil |
| c) Doors and windows | - Nil |
| d) Wood work wrought & put up | - Nil |
| e) Roof | - Nil |
| f) Flooring | - Nil |
| g) Miscellaneous (Cracks etc.) | - Nil |
| 7 Any major defects noticed which will render the building unsafe in any manner | - Nil |
| 8 Whether the maintenance works have been done properly | - Yes |
| 9 Whether the structure is sound or not for conducting classes | - Sound under normal weather condition |

Note

1. The stability of the structure should be examined also with reference to location, attitude, intensity of wind, exposure to flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on **20.05.2023**..... and found to be fit/unfitnormal weather condition to conduct classes for the period **up to and including** **31.03.2024**..... for the reasons stated above.

Place: Eloor

Date: 23.05.2023



Signature:

[Handwritten Signature]
യമുന പി. ബി.

Designation: ഏഞ്ചിനീയർ

PEN - 355411

LID & EW

എലൂർ നഗരസഭ