FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

- 1 Name of Officer
- 2 Name of School
- 3 Location with name of Education
- 4 Classification of building as specified in column 4 of application for fitness certificate and size
- Shylaja.K.P
- St.Ann's Public School, Eloor
- Eloor Aluva, Aluva
- Three Storied Building Ground Floor

Classroom	1x7.20x6.00x3.70m
Chemistry Lab	1x12.23x7.20X3.70m
Reception, Library	1x12.23x7.20x3.70m
Store.	2x 3.4 x 2.88x3.70m

First Floor

Class room	3x6x7.20x3.70m
Staff room	1x300x7.20x3.70m
Computer room	1x12.23x7.20x3.70m
Physics Lab	1x7.20x6.00x3.70m
Botony lab	1x12.23x7.20x3.70m
Room for Guide	1x2.40x2.88x3.70m
Store for Lab	2x3.48x2.88x3.70m

Second Floor

CI.	5 7 20 (00 2 70
Class room	5x7.20x6.00x3.70m
Class room	1x7.20x6.00x3.70m
Store for lab	2x3.48x2.88x3.70m
Class room	1x3.00x7.20x3.70m
Biology lab	1x12.23x7.20x3.70m
Room	1x2.40x2.88x3.70

- 5 Period of which the certificate is issued
- 6 Nature of defect if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and windows
 - d) Wood work wrought & put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks etc.)
- 7 Any major defects noticed which will render the building unsafe in any manner
- 8 Whether the maintenance works have been done properly
- 9 Whether the structure is sound or not for conducting classes

- For the academic year 2024-25
- Nil



- Stymn's Public School Eloor, Udyogamandal



Sound under normal weather condition 683501

Note

- 1. The stability of the structure should be examined also with reference to location, attitude, intensity of wind, exposure to flood etc.
- 2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Place: Eloor

Date: 25..05.2024

Sign

Designation

പ്രത്യേഗ് എഞ്ചുവുകൾ അസിസ്റ്റ്വറ്റ് എഞ്ചുവുകൾ എലൂർ നഗരസഭ

Principal
St. Ann's Public School
Eloor, Udyogamandal

LO LO POGANIA

MANAGER
St. Ann's Public School
Eloor, Udyogamandal
Ernakulam - 683501